

The Story Of A Floor


Chapter 1.

This aircraft hangar needed upgrading. The first step was to prepare the surface using a fast, efficient vacuum shotblasting machine.



Chapter 2.

There was evidence of rising damp in the concrete so the floor was coated with Tremco Surface Damp Proof Membrane. This effective coating suppresses rising damp, allowing application of paints or other floor coverings.



Chapter 3.

Tremco Epoxicote heavy duty sealer was then applied to provide an extremely durable, chemical and fuel resistant floor which is easily cleaned.



Chapter 4.

The bright, attractive appearance transformed the hangar.

